1140 35th Street Place NE Conover, NC 28613 828-381-1360 ~ howardlaffon@gmail.com

PROPERTY INSPECTION REPORT

CLIENT: JOHN & JANE DOE

ADDRESS: 1234 MY DRIVE NE CITY/STATE: MY CITY, NC 286--

DATE OF INSPECTION: ----



This Inspection was performed in accordance with the Standards of Practice of the North Carolina Home Inspector Licensure Board.

We are a professional Real Estate Inspection Service. We provide ETHICAL DISCLOSURE in an easy to understand and pleasant manner. We DO NOT contract for repairs to the properties we inspect and therefore have no reason to find marginal or expensive repairs.

INTRODUCTION:

There is no such thing as a house which is in flawless condition, and we have yet to inspect one that did not need some work. Most homes have some flaws which are in need of repair. Don't be discouraged to learn how many repairs a home may require. In most cases such concern is entirely unwarranted. The purpose of this report is to reveal all visible flaws that are apparent on the day of the inspection. We, therefore, encourage our client's that although there may be some flaws, this doesn't mean that the house being inspected is not a worthy home.

Although proper care has been taken in performing this inspection, this inspection cannot be fully exhausted, nor does it imply that all components were inspected, or that every defect was discovered, when the property contains a number of similar items however, a representation of each shall be inspected. In conducting the inspection, this company, its agents, and report is to detect major visible problems. It is not intended for cosmetic evaluation.

This particular home was disclosed to be vacant. The sellers are not tenants or occupants of the home and therefore the buyer should budget for defective items that could only be discovered by disclosure from the sellers. The inspector makes every effort to locate as many defects as possible, however, when a home is vacant, defects that are typically discovered by evidence from daily use and loads may not be apparent. There is an added risk to the buyer when purchasing a home without seller disclosure especially when a home has been vacant for month/years. The home inspection should be considered preliminary and the buyer should request a second inspection after they have placed the home in service.

Shane Laffon

Shane Laffon, License #3294

Summary of Inspection:

The summary is not the entire report. The full report may include additional information of interest or concern to the client. It is strongly recommended that the client promptly read the complete report. For information regarding the negotiability of any item in this report under a real estate purchase contract, contact your North Carolina real estate agent or an attorney. Additional problems may or may not be noted in this report. The items below were found to be in need of repair, attention or further evaluation. All issues found in summary page(s) should be repaired by a qualified or licensed individual in that particular area.

- 1 The front porch brick has settled at the front door area and near the garage area. These areas may hold water during rains; monitor and repair as necessary.
 - A) Front doorbell is not operating; doorbell needs repaired or replaced for proper operation.
- 2 On exterior at side of the garage both of the garage doors both garage doors have some moisture damage to both exterior jambs and moldings at bottom at some areas on exterior of doors; damaged wood needs to be repaired properly or replaced to prevent further deterioration at these areas.
 - A) On exterior right side of the garage the brick wall is cracked and shifted near the front gutter downspout; needs further evaluation and repairs by a masonry specialist or licensed contractor.
- 3 On exterior around perimeter of house some of the gutters are dented, damaged and leak at seams; gutters need repaired or replaced for proper drainage during rains and to prevent any damage to house. Note: These are copper gutters.
 - A) On exterior around perimeter the inspector could not locate the ends of all the gutter downspout drain pipes where they penetrate in yard; ends of all gutter downspout drain pipes need to be located where in yard or piped need to be re-run, for proper drainage during rains-to prevent any moisture seepage into the foundation at these areas during rains.
 - B) On exterior around perimeter of house all of the gutter downspouts are not piped away from the foundation. All downspout drain pipes away from the foundation with black corrugated or PVC piping underground to penetrate in yard at least eight to ten feet away from the foundation.









Thursday, June 23, 2016 Page 2 of 21

Summary of Inspection:

The summary is not the entire report. The full report may include additional information of interest or concern to the client. It is strongly recommended that the client promptly read the complete report. For information regarding the negotiability of any item in this report under a real estate purchase contract, contact your North Carolina real estate agent or an attorney. Additional problems may or may not be noted in this report. The items below were found to be in need of repair, attention or further evaluation. All issues found in summary page(s) should be repaired by a qualified or licensed individual in that particular area.

- 4 On exterior around perimeter of house there is some moisture damage to the exterior trim at some areas (including but not limited to shingle strips, fascia boards, trim strips, soffits and fascia boards); damaged wood needs to be repaired properly or replaced.
- 5 On exterior at front side of house there is a hole in the foundation. This is likely where a foundation vent is missing in the foundation (for the crawlspace area at front left side of the house); foundation vent needs replaced at missing area for proper operation and to prevent any pests from entering at this area.
- 6 On exterior around perimeter of house the grade is low at some areas and slopes toward the foundation. Grade should slope away from the foundation at all areas on exterior to prevent any moisture seepage into the foundation at this area during rains. Either the grade needs to be built up with fill dirt to slope away from the foundation or some type of drainage system needs to be installed to divert water away from the foundation during rains
- 7 On exterior around perimeter of house there is some moisture damage to the wood siding and corner boards at some areas; damaged wood needs to be repaired properly or replaced to prevent further deterioration at these areas.
- 8 On exterior around perimeter of house there is moisture damage to some window sashes, sills, center stiles, brick moldings and shutters; damaged wood needs to be repaired properly or replaced to prevent further deterioration at these areas.
- 9 On exterior at rear side of house the electrical disconnect box for the outside air conditioner unit is loose from the exterior wall; electrical disconnect box needs secured to wall for safety purposes.










Thursday, June 23, 2016 Page 3 of 21

Summary of Inspection:


The summary is not the entire report. The full report may include additional information of interest or concern to the client. It is strongly recommended that the client promptly read the complete report. For information regarding the negotiability of any item in this report under a real estate purchase contract, contact your North Carolina real estate agent or an attorney. Additional problems may or may not be noted in this report. The items below were found to be in need of repair, attention or further evaluation. All issues found in summary page(s) should be repaired by a qualified or licensed individual in that particular area.

- 10 On exterior at rear side of house there is a very large tree that is too close to the foundation. The tree roots have lifted the concrete slab at this area and slab slopes toward the foundation. There is a crack in the rear foundation wall on interior of this area, as well as in the basement floor. This is likely due to the tree roots lifted and cracking these areas; needs further evaluation and repairs by a licensed contractor as well as at tree specialist. Then repair/remove as deemed necessary.
 - A) On exterior at rear side of house the left side basement glass sliding doors have some moisture damage to both exterior jambs and brick moldings at bottom; damaged wood needs to be repaired properly or replaced. This glass sliding door leaks at bottom due to the concrete slab lifting at this area and is allowing moisture to enter into door. Refer to slab (#10) for repairs.
 - B) On exterior at rear side of house the right side basement glass sliding doors (below the screen porch) have some moisture damage to both exterior jambs and brick moldings at bottom; damaged wood needs to be repaired properly or replaced. The bottom threshold is higher than the door and door leaks at bottom due to this; needs repairs.
 - C) The glass panes in both sets of the basement glass sliding doors are fogged. The insulated glass panes have lost the argon between the glass panes and will eventually cloud over. The insulated glass panes need to be repaired properly or replaced.
- 11 Rear screen porch the left side corner support post has shifted outward approximately one inch; support post needs secured properly at bottom to prevent further settlement.
 - A) Rear screen porch has some moisture damage to the wood trim that supports the screens; damaged wood needs to be repaired properly or replaced.









Thursday, June 23, 2016 Page 4 of 21

Summary of Inspection:

The summary is not the entire report. The full report may include additional information of interest or concern to the client. It is strongly recommended that the client promptly read the complete report. For information regarding the negotiability of any item in this report under a real estate purchase contract, contact your North Carolina real estate agent or an attorney. Additional problems may or may not be noted in this report. The items below were found to be in need of repair, attention or further evaluation. All issues found in summary page(s) should be repaired by a qualified or licensed individual in that particular area.

- 12 On interior of the garage the rear wall has pushed outward approximately two to three inches (possibly from a car hitting this wall). The bottom sill plate and wall are cracked at this area. The right side wall in garage the foundation has sunken down approximately one and one half inches, the brickwork has a large gap at this area. At the step into the house the concrete slab floor is cracked and has settled approximately one inch. The garage floor has been patched at some areas; needs further evaluation and repairs by a structural engineer, then repairs per engineers' protocol.
 - A) On interior of the garage the wall paneling is damaged at some areas; damaged paneling needs replaced.
 - B) On interior of the garage the overhead light fixtures are not operating, possibly bulbs or fixtures; fixtures needs repaired or replaced for proper operation.
- 13 Throughout interior of house some windows won't open (top and bottom sashes-these are double hung window-the top and bottom window sashes should open, possibly painted shut; needs repairs for safety purposes and proper operation.
- 14 Hall (full) bathroom the toilet runs continually, possibly hardware needs adjusted/repaired or replaced on interior of the toilet tank; needs repairs to prevent the toilet from running continually.
- 15 Throughout the main level of the house the floors are out of level at some areas and some of the hardwood floors are cupped at some areas. Refer to basement and/or crawlspace for any type of repairs
- 16 Kitchen sink faucet leaks at base of spout while operating, possibly hardware needs replaced on interior of handle; needs repairs to prevent faucet from leaking at spout while operating.
 - A) Kitchen range hood fan is noisy while operating and the hood fan light fixture is not operating, possibly bulb or fixture; hood fan fixture needs repaired or replaced.









Thursday, June 23, 2016 Page 5 of 21

Summary of Inspection:

The summary is not the entire report. The full report may include additional information of interest or concern to the client. It is strongly recommended that the client promptly read the complete report. For information regarding the negotiability of any item in this report under a real estate purchase contract, contact your North Carolina real estate agent or an attorney. Additional problems may or may not be noted in this report. The items below were found to be in need of repair, attention or further evaluation. All issues found in summary page(s) should be repaired by a qualified or licensed individual in that particular area.

16 – Continued...

- B) In the kitchen the trash compactor is not responding to controls; compactor needs repaired or replaced for proper operation.
- C) Kitchen has one drawer that is off of track; drawer needs secured to track for proper operation.

17 – Den fireplace has a gap at the firebox and on interior of the firebox there are cracks and gaps present and the damper handle is rusted on interior; needs further evaluation and repairs by a chimney sweep prior to use for wood burning.

- A) Den glass sliding door is difficult to operate (due to bottom rollers) and both glass panes are fogged in doors. The insulated glass panes have lost the argon between the glass panes and will eventually cloud over. Doors need to be repaired properly or replaced.
- B) Rear screen porch overhead fan fixture does not operate properly; fan fixture needs replaced for proper operation.
- C) Screen porch floor is higher at the outside wall than at house side. Floor is covered in carpet-view obscured; needs further investigation and repairs by a qualified individual.

18 – Throughout the second floor some of the floors are out of level and some wood floors are cupped. Refer to crawlspace and/or basement for any type of repairs.

- A) In the second floor hallway the ceiling sags at one area; needs repairs to prevent further sagging.
- 19 Second floor hall bathroom the light fixture over sink is not operating, possibly bulb or fixture; fixture needs repaired or replaced for proper operation.









Thursday, June 23, 2016 Page 6 of 21

Summary of Inspection:


The summary is not the entire report. The full report may include additional information of interest or concern to the client. It is strongly recommended that the client promptly read the complete report. For information regarding the negotiability of any item in this report under a real estate purchase contract, contact your North Carolina real estate agent or an attorney. Additional problems may or may not be noted in this report. The items below were found to be in need of repair, attention or further evaluation. All issues found in summary page(s) should be repaired by a qualified or licensed individual in that particular area.

20 – In basement the sub electrical panel has one double tapped breaker (right side-second breaker). These types of breakers are not designed for more than one wire to enter into and one breaker currently has two wires entering; needs repairs by a licensed electrician-for safety purposes, as this is a fire hazard.

- A) In basement there is a leak at a sewer clean out below the hall (half) bathroom; needs further evaluation and repairs by a plumber to prevent leaking.
- B) Basement rear wall and floor is cracked. Refer to #10 for repairs.

21 – Crawlspace has a crack in the foundation below the front door the block foundation wall is cracked at the step up; needs further evaluation and repairs by a licensed contractor or masonry specialist.

- A) In crawlspace it appears that some of the support piers do not have footings installed. This may be the cause of the floors being out of level throughout house; needs further evaluation and repairs by a licensed contractor or masonry specialist.
- B) Crawlspace below the hall (full) bathroom there is a leak at a sewer clean out pipe; needs further evaluation and repairs by a licensed plumber to prevent leaking.
- C) Crawlspace shows signs of moisture entering. Refer to grade and gutter downspouts for repairs on diverting water away from the foundation.
- D) Crawlspace has a black and yellow fungus present on the floor system and other components.
- E) Crawlspace has two foundation vents that are damaged; damaged foundation vents need repaired or replaced for proper operation and to prevent any pests from entering at these areas. These foundation vents are below grade level-not visible on exterior and need vent wells installed around vents on exterior of house to prevent any moisture from entering into the foundation at these areas during rains.











Thursday, June 23, 2016 Page 7 of 21

1140 35th Street Place NE Conover, NC 28613

(828) 381-1360 ~ E-Mail: howardlaffon@gmail.com

Inspection Agreement/Description

Clients: KERRY & NICOLE KAHILL	E-mail Address:	
Property Address: 2561 EAGLE DRIVE NE	Current Address:	
City/State: CONOVER, NC 28613	City/State:	
Date: <u>6-23-2016</u> Time: <u>9:00am</u>	Phone #:	
Type of Inspection Requested (check all applicable):		
X Standard Inspection Radon Test Water Test		
Ouoted Price: \$425.00		

*Prices subject to change without prior notice or if improper heated and/or finished square footage is quoted at time of inspection request.**We reserve the right to charge an additional fees for home that are greater than forty years old, foreclosures, investment properties, estates, homes in distress at the time of the inspection-upon visible inspection of the property**

Inspection Agreement/Description:

To include the following: Report general condition of visible limited evaluation of the building structure, its components, appliances, style of building on the actual date of inspection. Inspection will be performed in accordance with the North Carolina Home Inspection Licensure Board Standards of Practice. This inspection includes 300-500 items limited to exposed visual examination of the following: site, foundation, structure, roof, framing, electrical, plumbing, heating, attic, garages, exterior, interior, walls, doors, windows, ceilings, fireplaces, chimneys, and appliances.

The inspection is intended to assist in the evaluation or overall condition of the building and its components on date of inspection. The results of inspection are not intended to make any representation regarding latent or concealed defects that may or may not exist. No warranty or guarantee is expressed or implied. No representation is made to how long equipment will continue to function.

Limits: Although proper care has been taken in performing this inspection, this inspection cannot be fully exhausted, nor does it imply that all components were inspected, or that every defect was discovered, when the property contains a number of similar items however, a representation of each shall be inspected. In conducting the inspection, this company, its agents, and report is to detect major visible problems. It is not intended for cosmetic evaluation. No compliance with any code is intended with this inspection. The inspector is not an expert in every craft or profession. The inspector cannot determine when renovations, additions or any type of replacements or adjustments have been made to structure(s). Permit information can be obtained at the county offices. This type inspection and report is based upon the experience of the individual inspector. The client agrees to assume all risks for conditions which are concealed from view or inaccessible.

Exclusions: Specific exclusions include, but are not limited to cost estimates, swimming pools, hot tubs, spas, saunas, steam rooms, water conditioning equipment, humidifiers, septic systems, drain fields, underground sewage connections, fuel tanks, wells and components, telephone systems, gas logs, concealed plumbing and electrical, motion sensors, obscured areas, central vacuum, heated flooring, storm windows or doors, wall insulation, detached buildings, recreational equipment, thermostats, technical complex systems, termites, bats, pests, structural, geological, irrigation/sprinkler systems, TV antennas, zoning, asbestos, lead, radon, formaldehyde, electro-magnetic, water softeners, cosmetic finishes and conditions, bodily fluids, previous substance abuse in house, awnings, portable equipment, motion detectors, security systems, dry rot, mold, fungus. Nor does it include heat exchangers, air conditioner coils, inside of duct work, heat in summer months and air conditioner in winter months, carbon monoxide, unique systems, technically complex systems, solar systems, self-cleaning ovens, refrigerators, washing machines, dryers and drain pipes, alarm systems, intercom systems, elevators, dumbwaiters, generators or low voltage systems.

Liabilities: The client requests the standard inspection of exposed and readily accessible surfaces of the building. The inspector's liability for errors and omissions is limited to a refund of fees paid. The liability of the inspector, his company, and his employees are also limited to fees paid. The liability limitation upon client and their spouses, heirs, principles, etc. or any kind of mistakes or omissions to fees paid. The Client agrees to accept a refund of fees paid as full settlement of any and all claims which may arise from this inspection report.

Confidentiality: This report is confidential and is not to be copied by any other party without the expressed written consent of this company. Specific use or reliance upon the report by other parties, or other transactions is unauthorized and strictly prohibited. All rights reserved.

Dispute: If client has complaints against the inspection or inspector, before any alteration, repair or replacement, the client shall notify this company and permit an inspection of conditions which gave rise to the complaint, by the inspector. The client agrees to hold the inspector harmless for all claims relating to conditions that are altered or repaired without said notice of the inspection. All parties agree that no action can be brought to recover damages for the inspection for more than one year after delivery of this report.

Thursday, June 23, 2016 Page 8 of 21

1140 35th Street Place NE Conover, NC 28613 (828) 381-1360 ~ E-Mail: howardlaffon@gmail.com

Inspection Agreement/Description

Acknowledgment:

This report is performed expressly for the sole, confidential and exclusive possession of the Client. This report is confidential and is not to be copied by any other party without the expressed written consent of this company. Specific use or reliance upon the report by other parties, or other transactions is unauthorized and strictly prohibited. All rights reserved.

	quested (check all applic			
X Home Inspection	nRadon Test	Water Test	Lead-based P	aint Test
Total Charges:	\$425.00			
_				
Paid Check				
	me of the home inspection, i	inless other arran	gements have been made p	rior to the inspection.
**Buyer is responsible fo	r au inspection jees. to charge an additional fees	for homes that are	a avaatan than fonty yaans a	ld forgalosuras invastment
	omes in distress at the time of			
F. •F•······		, _F	r · · · · · · · · · · · · · · · · · · ·	Fishers
Closing Date:				
Q 1' Q 1' C	0 1 11			
Credit Card Information	n: Card #:			
	Expiration Date: Security Code (CVS): _			
	7' 0 1			
*Inspection fees are due	within 30 days of the inspec	tion. Your credit c	ard will be processed if pay	ment is not received within thirty
days of the inspection.				
*There will an 18% late j	fee charged on all outstandi	ng balances after .	<u>30 days.</u>	
Will you be attending the	inspection? X Yes	No		
	the inspection payment arr		ed to be made prior to the i	nspection.
••		o .	•	
	for inspector to set up			
Buyer's Agent:	My Agent			
Agents Phone #:				
Listing Agent.	I our Agent			
Agents Phone #:	Occupied			
House occupancy: _	Occupied	X_Vacant	Foreclosure	X Estate
Buyer is responsible j	for all inspection fees			
I The Client have read a	inderstand, agree to the abov	e terms and condit	ions, agree to pay for service	es rendered and agree to carefully
read the entire inspection		e terms and condit	ions, agree to pay for servic	es rendered and agree to carefully
r	·F·			
Client:			Date:	
e n	1 11			
Inspector: Share	Laffon, Inspector, NC Licens		Date:	
Shane I	Laffon, Inspector, NC Licens	e #3294		

Thursday, June 23, 2016 Page 9 of 21

INFORMATION/STRUCTURE

INFORMATION ABOUT INSPECTION:

Please read the following carefully:

Items followed by an (X) Recommended Repairs: these are items brought to the client's attention by the inspector. These items are highlighted in yellow and should be repaired by a licensed contractor or trades person in that specific area. The inspector may document (note) smaller issues that may not warrant repairs at time of inspection. These notes will not be highlighted in the report. The client should obtain a termite report by a licensed pest control company. By law only a licensed pest control company can inspect and report infestation.

If you were not able to be present during inspection:

This report may contain some information that you may not understand or have questions about. Therefore, you may want a verbal consultation with the inspector. If you so choose, you may call our office to talk with the inspector about the inspection.

PRESENT FOR INSPECTION: X_BuyerSellerX_Buyers AgentListing AgentInspector onlyDual AgentOtherRelative
Information:
Type of Building: X ResidentialCondominiumTown homeDuplexApartment(s)CommercialOther
STYLE OF BUILDING: X Ranch 1.5 Story Two story Three story Split foyer Split level Cape cod Duplex Townhome Condominium A-frame Manufactured home Bungalow Contemporary
APPROXIMATE AGE OF STRUCTURE: 1974 Yrs. APPROXIMATE AGE OF ROOF: 2007 (per MLS) Yrs.
BUILDING OCCUPANCY: X Vacant Occupied X Furnished Infurnished Foreclosure New Construction Estate
WEATHER CONDITIONS: Temperature 78 ° F X Clear Rain Cloudy Frost Foggy Other
Rain/Snow in last 3 days: Yes X No
POWER: X On Off WATER: X On Off GAS: On Off
Type of Inspection Performed:
X Standard Inspection
Radon test
Water test
Lead-based paint test

Thursday, June 23, 2016 Page 10 of 21

EXTERIOR OF SITE:

EXTERIOR GRADE:Almost level _X Gentle slopeTerraceSteep slope
InspectedX_RepairInvestigateNot InspectedNot Applicable
Erosion noted:Recommend soil to be 4" below siding:
Drainage needs correction by grading specialist at:Recommend terrace at:
<u> </u>
Notes: Refer to summary pages. *Drains observed - not tested.
"Drains observed - not tested.
RETAINING WALLS:BrickBlockWoodStoneOther
InspectedRepairInvestigateNot InspectedX Not Applicable
No weep holes observed Settled at: Leaning at:
No weep holes observed Settled at: Leaning at: Damaged at: Recommend railing Moisture damage at:
Notes:
EXTERIOR LANDSCAPING:
Inspected _X_RepairInvestigateNot InspectedNot Applicable
X Trees near structure at: Rear X Trees/Shrubbery may need trimming to prevent damage to home
X Shrubbery to close to structure at: Some Vines obscuring view at:
Trees or shrubbery may cause moisture problems at foundation at:
Mulch against foundation may draw termites to this area at:
Notes:
STEPS: X Wood Concrete Masonry Metal Tile Stone Trex/Composite Other X Inspected Repair Investigate Not Inspected Not Applicable Wood not treated for exterior use: Weathering/ corroding: Step treads damaged/missing/cracked/loose: Settled: Handrail not to standard height: Handrail damaged/missing/loose: Moisture damage at: Steps not proper rise/run: Notes:
SIDEWALKS: X Concrete Brick Gravel Tile Stone Asphalt Earth Rock Other
X Inspected Repair Investigate Not Inspected Not Applicable
X Cracks noted Larger cracks at: Settled/ lifting Roots noted under sidewalk
Slopes toward house, should slope away Dirt undermined below slab Missing/Loose:
Notes:
DRIVEWAY: X Concrete Brick Gravel Tile Flagstone Asphalt Earth Other X Inspected Repair Investigate Not Inspected Not Applicable X Cracks noted Larger cracks at: Settled/lifting Roots noted under driveway Slopes toward house, should slope away Dirt undermined below slab Culvert clogged at end of driveway Notes:
GUTTERS: None Partial X Complete At end of life expectancy
Inspected
X Corrosion noted excessive/minor at: Copper gutters Downspout not in drain pipe at:
Gutter loose from fascia board at: X Damaged gutters/downspout at: Some
Downspouts/Gutters missing/loose/apart at:Gutters need cleaning
Downspouts need to be piped away from foundation and buried underground to penetrate in yard away from foundation
X Inspector could not locate ends of gutter downspouts where they penetrate in yard; ends need to be located
Notes: Refer to summary pages.

*The inspector cannot always locate the ends of all gutter downspout drain pipes where they penetrate in yard. Ends of all downspout drain pipes need to be located in yard for proper drainage during rains. Otherwise you will have water seepage into the foundation during rains. Gutters are not tested for leakage or slope.

Thursday, June 23, 2016 Page 11 of 21

EXTERIOR OF STRUCTURE GARAGE/CARPORT:

EXTERIOR WALLS: X Wood Stucco X Brick Hardboard Aluminum Vinyl Stone Eifs Stucco Asbestos Hardie board X Columns X Block Stucco board
InspectedX_Repair _X_InvestigateNot InspectedNot Applicable
X Cracks noted X Horizontal/Vertical/Stepping cracks at: Garage, Rear side Recommend sealing gaps/holes
X Patching noted X Moisture/Insect damage at: Siding-perimeter Earth to wood/siding contact at: Siding damaged/out of track/missing/loose at: View obscured due to foliage
Slding damaged/out of track/missing/loose at: view obscured due to foliage
Notes: Refer to summary pages. *Presence of wall insulation not verified.
"Freschee of wan insulation not verified.
TDIM & FAVES, V Wood Motal Masonry Vinyl Hardboard
TRIM & EAVES: X Wood Metal Masonry Vinyl Hardboard Inspected Not Inspected Not Applicable
InspectedX_RepairInvestigateNot Inspected Not Applicable Not Some wood trim, fascia boards, soffits, shingle strips, etcperimeter
Missing/Loose trim at: Not visible because of foliage
Notes: Refer to summary pages.
, F.
PATIOS: X Concrete Brick Tile Stone Other
Inspected X Repair Investigate Not Inspected X Not Applicable
Inspected X Repair Investigate Not Inspected X Not Applicable Cracks noted Larger cracks at: Bricks/Stones loose/missing at:
X Settled/lifting X Slopes toward house, should slope away Dirt undermined below slab
Notes: Refer to summary pages.
PORCHES: Concrete Wood Tile X Brick Stone
InspectedRepairInvestigateNot InspectedNot Applicable
Inspected Repair Investigate Not Inspected Not Applicable Gaps need sealant Moisture/Insect damage at: Settled/Cracked/deteriorated Cracks noted Loose/missing/damaged pickets/railing at: X Settled: Front porch
Cracks noted Loose/missing/damaged pickets/railing at:
Notes: Refer to summary pages.
DECKS: X Treated wood Non treated wood Concrete Trex/Composite
InspectedX_RepairInvestigateNot InspectedNot Applicable
Not bolted to structureFlashing missing X Posts leaning/damaged/missing at: 1-screen porch X Cracked/broken/damaged wood at: Screen trim stripsNot built to any today's standardsOutside floor band pulling away
All floor joists need joist hangers installed at each end of every floor joist below floor system X Slopes toward house: Screen porce
Loose/damaged/warped/broken floor boards/pickets/handrails/guardrailsLow clearance-cannot fully inspect
Notes: Refer to summary pages. Rear screen porch floor is covered in carpet-view obscured.
GARAGE: X Attached Detached 2 # of cars No parking structure Covered by floor covering/storage
InspectedX_RepairInvestigateNot InspectedNot Applicable
CARPORT:Attached# of carsNo parking structure Covered by floor covering/storage
Notes: Refer to summary pages.
*Detached garages or any buildings not connected to the dwelling are not inspected during a home inspection.
FLOOR: X Concrete slab Asphalt Other Covered by floor covering/storage
X Inspected Repair Investigate Not Inspected Not Applicable
X Cracks noted Large cracks Slopes toward house-should slope away Settled
Notes: Refer to summary pages.
GARAGE DOORS: X Wood Metal Unable to test
InspectedX_RepairInvestigateNot InspectedNot Applicable
Door needs adjustment/does not sealRecommend lubricating hardwareDoor damagedJambs damaged
2x6 that holds operator tracks is pulling loose from wallBrick molding damagedWeather stripping damaged/too short
Notes: Refer to summary pages.
AUTOMATIC OPENERS: 2 # of openersUntested
X Inspected Repair Investigate Not Inspected Not Applicable
Operator button has to be held down for door to retreet Not operating Loose

Thursday, June 23, 2016 Page 12 of 21

EXTERIOR/FOUNDATION:

PERIMETER FOUNDATION:Concrete _X _Brick _X _BlockStone Full Basement/Cellar X Partial Basement/Cellar X Crawlspace Concrete Slab Closed (retrofitted) Crawlspace
CRAWLSPACE ACCESS LOCATED AT: Basement-front wall Crawled No access Observed from access only with flashlight Could not access-low clearance/duct work/etc.
InspectedX_RepairInvestigateNot InspectedNot Applicable
X Cracks noted X Larger cracks Damaged walls/piers Could not inspect-low clearance at:
Not draining properly at: Efflorescence noted at: X Foundation vents need vent wells installed at: 2-Crawlspace
Efflorescence noted at: X Foundation vents need vent wells installed at: 2-Crawlspace V. Foundation vents (a) an artifulation (b) and the language of the foundation vents need vent wells installed at: 2-Crawlspace Description and the language of the la
X Foundation vent(s) apart/missing/loose/damaged at: 1-front, 2-Crawlspace Recommend to have vent fan(s) installed X Insulation installed wrong side up at: Passement Crawlspace Insulation missing/damaged/loose in some grees
X Insulation installed wrong side up at: Basement, Crawlspace Insulation missing/damaged/loose in some areas Access door/frame missing/damaged at: Sump pump observed /not tested
Access door/frame missing/damaged at: Sump pump observed /not tested Insulation present below floor system: X Yes No N/A Vapor retarder installed: Yes X No N/A
Notes: Refer to summary pages.
Type of Framing:
FRAMING: X Wood beams Steel beams Superior Walls
SUPPORTING PIERS: Wood X Steel X Masonry (Brick/Block) Rock
SUB FLOOR: X Wood Boards N/A
FLOOR FRAME: X JoistsTrussesEngineered LumberSlab construction
Inspected V Densin Inspetients Not Inspected Not Applicable
Damaged sub floor at: Damaged beams at: Damaged beams at:
Damaged sub floor at: Damaged beams at: Damaged piers X Piers need footings installed: Crawlspace Damaged sills/ledgers at: X Fungus noted on floor system
Damaged floor joists at: Framing to close to earth at:
Damaged floor joists at:Framing to close to earth at: Damaged outside floor band at:Piers are not in non-load bearing form at:
Notes: Refer to summary pages. Crack noted a step up in foundation at front door in crawlspace.
BASEMENT/LOWER SLAB: X Concrete Other * Slabs visual only
Inspected Repair X Investigate Not Inspected Not Applicable
InspectedRepairX_InvestigateNot InspectedNot ApplicableSlab not visible due to floor coveringDehumidifier presentX_Cracks noted at: Basement walls and floors-rear to tree at rear
Inspected Repair X Investigate Not Inspected Not Applicable Slab not visible due to floor covering Dehumidifier present X Cracks noted at: Basement walls and floors-rear to tree at rear Moisture noted at: Perimeter expansion joints noted: Notes: Refer to summary pages. No guarantee is made if basement leaks, all water proofing and drains are under ground and cannot be seen.
Inspected Repair X Investigate Not Inspected Not Applicable Slab not visible due to floor covering Dehumidifier present X Cracks noted at: Basement walls and floors-rear to tree at rear Moisture noted at: Perimeter expansion joints noted: Notes: Refer to summary pages. No guarantee is made if basement leaks, all water proofing and drains are under ground and cannot be seen. ATTIC: Complete access No access Observed from access only with flashlight Could not access (due to storage)
InspectedRepairX_InvestigateNot InspectedNot ApplicableSlab not visible due to floor coveringDehumidifier presentX_Cracks noted at:Basement walls and floors-rear to tree at rearMoisture noted at:Perimeter expansion joints noted:Notes: Refer to summary pages. No guarantee is made if basement leaks, all water proofing and drains are under ground and cannot be seen. ATTIC:Complete accessNo accessObserved from access only with flashlightCould not access (due to storage) ATTIC ACCESS LOCATED AT:Garage &2^nd floor Hall
InspectedRepairX_InvestigateNot InspectedNot ApplicableSlab not visible due to floor coveringDehumidifier presentX_Cracks noted at:Basement walls and floors-rear to tree at rearMoisture noted at:Perimeter expansion joints noted:Notes: Refer to summary pages. No guarantee is made if basement leaks, all water proofing and drains are under ground and cannot be seen. ATTIC:Complete accessNo accessObserved from access only with flashlightCould not access (due to storage) ATTIC ACCESS LOCATED AT:Garage &2^nd floor Hall

Thursday, June 23, 2016 Page **13** of **21**

ROOF SYSTEM:

SLOPED ROOFS:
TYPE: X Composition shingles Wood shingles Wood shake At end of life expectancy
X Inspected Repair Investigate Not Inspected Not Applicable
Nearing end of life expectancyNumber of layers of shinglesMissing/Damaged/Cracked shingles at:
Weak/Buckled/Humps/Damaged roof sheathing at: Cupping/curling shingles at:
Weak/Buckled/Humps/Damaged roof sheathing at: Nail heads/staples exposed to weather: Some/Many patches noted: Vent ridge damaged/loose: End caps) missing at:
Some/Many patches noted: Vent ridge damaged/loose: End caps) missing at:
Notes:
* Some leaks cannot be detected with visual inspection.
ELACHING
FLASHING:
TYPE: X Metal Mastic X Rubber boot Not visible
X Inspected Repair Investigate Not Inspected Not Applicable
Needs flashed/sealed (mastic) at: Improper installation at:
Needs cricket installed at: Needs repaired/replaced at: Rubber boot split/damaged: Rubber boot split/damaged:
Notes:
INOTES.
SLOPED ROOFS:
TYPE: Slate Metal Tile Clay At end of life expectancy Inspected Repair Investigate Not Inspected X Not Applicable
Moisture stains at:
Notes:
11000
BUILT-UP ROOFS:
BUILT-UP ROOFS: TYPE:Tar gravelSingle plyRoll composition _X _Rubber: 2 nd floorTarAt end of life expectancy
BUILT-UP ROOFS: TYPE:Tar gravelSingle plyRoll composition _X _Rubber: 2 nd floorTarAt end of life expectancy X _Inspected RepairInvestigate
BUILT-UP ROOFS: TYPE:Tar gravelSingle plyRoll composition _X _Rubber: 2 nd floorTarAt end of life expectancy X _Inspected RepairInvestigate
BUILT-UP ROOFS: TYPE:Tar gravelSingle plyRoll composition _X_Rubber: 2 nd floorTarAt end of life expectancy X_InspectedRepairInvestigateNot Inspected _X_Not Applicable Nearing end of life expectancyBare areas noted:Separating at seams Exposed/popped nailsEvidence of water standingCrackingBlistersWeak areasRecommend cleaning
BUILT-UP ROOFS: TYPE:Tar gravelSingle plyRoll composition _X _Rubber: 2 nd floorTarAt end of life expectancy X _Inspected RepairInvestigate
BUILT-UP ROOFS: TYPE:Tar gravelSingle plyRoll composition _X _Rubber: 2 nd floorTarAt end of life expectancyX _InspectedRepairInvestigateNot Inspected _X _Not ApplicableNearing end of life expectancyBare areas noted:Separating at seamsExposed/popped nailsEvidence of water standingCrackingBlistersWeak areasRecommend cleaning Notes:
BUILT-UP ROOFS: TYPE:Tar gravelSingle plyRoll composition _X_Rubber: 2 nd floorTarAt end of life expectancy X_InspectedRepairInvestigateNot Inspected _X_Not Applicable Nearing end of life expectancyBare areas noted:Separating at seams Exposed/popped nailsEvidence of water standingCrackingBlistersWeak areasRecommend cleaning
BUILT-UP ROOFS: TYPE:Tar gravelSingle plyRoll composition _X _Rubber: 2 nd floorTarAt end of life expectancyX _InspectedRepairInvestigateNot Inspected _X _Not ApplicableNearing end of life expectancyBare areas noted:Separating at seamsExposed/popped nailsEvidence of water standingCrackingBlistersWeak areasRecommend cleaning Notes:
BUILT-UP ROOFS: TYPE:Tar gravelSingle plyRoll composition _X _Rubber: 2 nd floorTarAt end of life expectancyX _InspectedRepairInvestigateNot Inspected _X _Not ApplicableNearing end of life expectancyBare areas noted:Separating at seamsExposed/popped nailsEvidence of water standingCrackingBlistersWeak areasRecommend cleaning Notes:
BUILT-UP ROOFS: TYPE:Tar gravelSingle plyRoll composition _X _Rubber: 2 nd floorTarAt end of life expectancyXInspectedRepairInvestigateNot InspectedXNot ApplicableNearing end of life expectancyBare areas noted:
BUILT-UP ROOFS: Type:Tar gravelSingle plyRoll composition _X_Rubber: 2 nd floorTarAt end of life expectancyX_InspectedRepairInvestigateNot Inspected _X_Not ApplicableNearing end of life expectancyBare areas noted:Separating at seamsExposed/popped nailsEvidence of water standingCrackingBlistersWeak areasRecommend cleaning Notes: FIREPLACES/CHIMNEYS: FIREPLACES:InspectedX_RepairInvestigateNot InspectedNot Applicable
BUILT-UP ROOFS: Type:Tar gravelSingle plyRoll composition _X_Rubber: 2 nd floorTarAt end of life expectancyX_InspectedRepairInvestigateNot Inspected _X_Not ApplicableNearing end of life expectancyBare areas noted:Separating at seamsExposed/popped nailsEvidence of water standingCrackingBlistersWeak areasRecommend cleaning Notes: FIREPLACES/CHIMNEYS: FIREPLACES:InspectedX_RepairInvestigateNot InspectedNot Applicable
BUILT-UP ROOFS: TYPE:Tar gravelSingle plyRoll composition _X_Rubber: 2 nd floorTarAt end of life expectancyX_InspectedRepairInvestigateNot Inspected _X_Not ApplicableNearing end of life expectancyBare areas noted:Separating at seamsExposed/popped nailsEvidence of water standingCrackingBlistersWeak areasRecommend cleaning Notes: FIREPLACES/CHIMNEYS: FIREPLACES:InvestigateNot InspectedNot Applicable LOCATION: #1Den #2 #3 #4 Type of unit: _X_MasonryMetalPrefabricatedWood stove Gas log fireplace (vented/non vented) Fire box materials: _X_Fire brickMetalNon fire brick _X_Cracks noted (minor/severe) _X_Mortar cracking falling from joints
BUILT-UP ROOFS: TYPE:Tar gravelSingle plyRoll composition _X_Rubber: 2 nd floorTarAt end of life expectancyX_InspectedRepairInvestigateNot Inspected _X_Not ApplicableNearing end of life expectancyBare areas noted:Separating at seamsExposed/popped nailsEvidence of water standingCrackingBlistersWeak areasRecommend cleaning Notes: FIREPLACES/CHIMNEYS: FIREPLACES:InvestigateNot InspectedNot Applicable LOCATION: #1Den #2 #3 #4 Type of unit: _X_MasonryMetalPrefabricatedWood stove Gas log fireplace (vented/non vented) Fire box materials: _X_Fire brickMetalNon fire brick _X_Cracks noted (minor/severe) _X_Mortar cracking falling from joints
BUILT-UP ROOFS: TYPE:Tar gravelSingle plyRoll composition _X _Rubber: 2 nd floorTarAt end of life expectancyXInspectedRepairInvestigateNot InspectedXNot Applicable
BUILT-UP ROOFS: TyPE:Tar gravelSingle plyRoll composition _X_Rubber: 2 nd floorTarAt end of life expectancyX_InspectedRepairInvestigateNot Inspected _XNot ApplicableNearing end of life expectancyBare areas noted:
BUILT-UP ROOFS: TYPE:Tar gravelSingle plyRoll composition _X _Rubber: 2 nd floorTarAt end of life expectancyXInspectedRepairInvestigateNot InspectedXNot Applicable
BUILT-UP ROOFS: TyPE:Tar gravelSingle plyRoll composition _X_Rubber: 2 nd floorTarAt end of life expectancyX_InspectedRepairInvestigateNot Inspected _XNot ApplicableNearing end of life expectancyBare areas noted:
BUILT-UP ROOFS: TYPE:Tar gravelSingle plyRoll composition _X _ Rubber: 2 nd floorTarAt end of life expectancyX _ InspectedRepairInvestigateNot InspectedXNot Applicable
BUILT-UP ROOFS: TYPE:Tar gravelSingle plyRoll composition _X _ Rubber: 2 nd floorTarAt end of life expectancyX _ InspectedRepairInvestigateNot InspectedXNot Applicable
BUILT-UP ROOFS: TYPE:Tar gravelSingle plyRoll composition _X_Rubber: 2 nd floorTarAt end of life expectancy
BUILT-UP ROOFS: TYPE:Tar gravelSingle plyRoll composition _X_Rubber: 2nd floorTarAt end of life expectancyX_InspectedRepairInvestigateNot Inspected _X_Not ApplicableNearing end of life expectancyBare areas noted:Separating at seamsExposed/popped nailsEvidence of water standingCrackingBlistersWeak areasRecommend cleaningNotes: FIREPLACES/CHIMNEYS: FIREPLACES:InspectedX_RepairInvestigateNot InspectedNot ApplicableLOCATION: #1Den #2 #3 #4 Type of unit: _X_MasonryMetalPrefabricatedWood stove Gas log fireplace (vented/non vented)
BUILT-UP ROOFS: TYPE:Tar gravelSingle plyRoll composition _X_Rubber: 2 nd floorTarAt end of life expectancy
BUILT-UP ROOFS: TYPE: _Tar gravelSingle plyRoll composition X_Rubber: 2nd floor _TarAt end of life expectancy X_InspectedRepairInvestigateNot Inspected XNot Applicable
BUILT-UP ROOFS: TYPE:Tar gravelSingle plyRoll composition _X_Rubber: 2 nd floorTarAt end of life expectancy

Thursday, June 23, 2016 Page **14** of **21**

ELECTRICAL/FUEL/SMOKE DETECTORS/CARBON MONOXIDE DETECTORS:
EXTERIOR SERVICE: X Underground Overhead
of lines into house: 3 Fuses X Breakers Other/3-phase system X Inspected Repair Investigate Not Inspected Not Applicable
X Inspected Repair Investigate Not Inspected Not Applicable
Wires bare/loose from meter to mastNo proper loopLines in trees/too lowEntrance meter box loose from wall
Notes:
MAIN ELECTRICAL PANEL AND SUB PANEL BOXES: Exterior panel opened X Interior panel opened
LOCATION OF MAIN PANEL: EXTERIOR-REAR LOCATION OF SUB PANELS: 2-BASEMENT
LOCATION OF MAIN PANEL: EXTERIOR-REAR LOCATION OF SUB PANELS: 2-BASEMENT Inspected X Repair Investigate Not Inspected Not Applicable
SIZE OF MAIN ELECTRICAL SERVICE: 150 amp (220 volt) Size was not marked
Service entry conductor materials: AL System seems to be outdated, recommend to have checked by a licensed electrician
Missing front cover panel Terminal has corrosion Recommend labeling breakers Damaged/Broken/Defective Breaker
Missing front cover panelTerminal has corrosionRecommend labeling breakersDamaged/Broken/Defective BreakerY Double tapping on1circuit(s) noted at:Sub panel Missing cover panel Improper/missing screws installed in panel:
Main electrical panel is not grounded Old knob and tube wiring noted Open breaker/knockout holes in panel
Improper wiring noted at: Electrical coating damaged on wiringRecommend protecting wiring at:
Exposed/abandoned/spliced wires located at:
Need to have wires in junction box at:
Need to have wires in junction box at:
Junction box without cover at:
OUTLETS AND SWITCHES:
Electrical not grounded at: Electrical outlet/switch/plate damaged at:
Electrical outlet not operating/loose from wall/wired reverse polarity at:
No GFCI outlets noted at: GFCI outlet defective/not operating at:
No GFCI outlets noted at:
LIGHTS:
Fixture missing/broken/loose/damaged at: Could not determine what light switch operates
Fixture missing/broken/loose/damaged at: Could not determine what light switch operates Kristure not operating at: Garage, Screen porch-fan, 2 nd floor hall bath Missing hardware at:
Dimmer knob missing/does not dim light at: Overhead fan noisy/wobbles while operating at:
*Sometimes bulbs can be the reason light fixtures are not working, please verify prior to closing.
*GFCI outlets are not required in all homes, it is recommended to have in bathrooms, kitchens and on exterior.
*Security systems are not a part of this inspection nor are low volt systems.
Notes:
SMOKE DETECTORS:
X Inspected Repair Investigate Not Inspected Not Applicable
Could not test - part of security system/due to height Tested Not tested
Did not respond to test at: None found Chirping; possibly needs batteries
Recommend installing at:Missing on ceiling at:
Notes:
CARBON MONOXIDE DETECTORS:
InspectedRepairInvestigateNot Inspected Not Applicable
Could not test - part of security system/due to height: Tested Not tested
Did not respond to test at: None found X Recommend installing at: One on each level
Notes:
*The inspector recommends installing at least one carbon monoxide detector on each level in house if house has any type of gas
appliances installed or has an attached garage that stores vehicles on a regular basis-for safety purposes.
FUEL:
VENT PIPING MATERIALS:PVC Metal
VENT PIPING MATERIALS:PVC MetalInspectedRepairInvestigateNot InspectedX Not Applicable
VENT PIPING MATERIALS:PVC MetalInspectedRepairInvestigateNot InspectedX Not ApplicableGas meter located at: LP Tank located at:
VENT PIPING MATERIALS:PVC MetalInspectedRepairInvestigateNot InspectedX Not Applicable

Thursday, June 23, 2016 Page 15 of 21

*Underground oil tanks need checked for any type of leakage below ground and repair as necessary.

*Tests for gas leaks & pipe sizing are not performed. It is advised that local gas company service for all gas appliances prior to closing. The gas company tests can reveal problems that may not be discovered with a limited visual property inspection.

HEATING:

FURNACE LOCATION:	#1 Basement	#2	#3			
Type						
TYPE:				D 11 (ъ.,	***
Heat Pump Electric F	GurnaceGas	FurnaceOil Furi	naceForced	Radiant	_Boiler	_Water Heater
Fig. Floring	Car O:	D	Waad	Can back		
FUEL:Electric	_GasOi	lPropane	Wood	Gas back-up		
GENERAL CONDITION:						
Inspected X Repair	r Investiga	te Not Inspected	Not Applica	hle		
Not responding to controls	mivestiga		mend to have chec		Contractor	
Suggest cleaning/servicing		Fan keeps		nea oy a 11 v 11c	Contractor	
Makes noise			t, may have limited	l life		
X Signs of leakage: Basement	t-condensation lir		stalled below furn			
Water standing in overflow			temperature too hig		t	
Notes:						
*Inspector does not light pilo						
*During summer months the	inspector canno	t check furnace unit	for operation if ou	itside tempera	ture is above	e 60 degrees.
BURNER:						
		Not Inspected		ble		
Closed system cannot inspe	ct	_Pilot not lit/no power	r			
Flame color not normal	_	Rust flakes noted				
Fluctuation of flame noted		_Soot noted				
Notes:						
*In most cases the inspector	is unable to dete	ect cracks or holes in	heat exchangers;	this can only b	e accomplisi	ned by dismantlin
unit.						
VENTING:	T	NT / T	W7 W7 4 A 11 1			
	Investigate	Not Inspected		ble		
Apparent back draft Flue to close to combustible		_Pilot not lit/no power Rust/soot noted				
Notes:		_Kust/soot noteu				
Notes.						
COLD AIR RETURN:						
	Investigate	Not Inspected	Not Applicabl	e		
Returns to close to each other			damaged on return			
Grills damaged		Other				
Notes:						
DISTRIBUTION:						
TYPE: X Duct work	Pipes	Radiators	Baseboard	Ceiling (v	wires)	Unit
X Inspected Repair	Investigate	Not Inspected	Not Applicabl	e		_
No heat/air source at:		Duct work dama	ged/loose/has hole	s at:		
Low/No air volume noted a	at:	Vent regi	ster not correct size	e at:		
Low/No air volume noted a Vent register Missing/Dam	aged/Loose from	ceiling/wall at:		Control kn	obs missing:	
Leak in pipes at:		Controls not operat	ing at:			
Notes:						
*The inspector cannot view the					tion of the h	eat system or its
components contact a license	d HVAC contrac	ctor in addition to the	e nome inspection.	•		
FILTERS:		_				
Located at: #1 Furnace X Inspected Repair	#2 _	Furnace	#3	#4		
X Inspected Repair	Investigate	Not Inspected	Not Applicabl	e	: :	. J
Needs changed at:		iviissing at:		wrong	g size installe	ea
Notes: *Filters need to be changed n	nonthly or as ins	tructed by the manuf	facturer			
I meets need to be changed if	nonung or as ms	a acted by the manul	inctui Ci .			

Thursday, June 23, 2016 Page **16** of **21**

AIR CONDITIONING/PLUMBING:

AIR CONDITIONER:

LOCATION:	#1 <u>Ex</u>	terior	#2 <u>Ext</u>	erior		#3	
TYPE: XX	_Part of He	at Pump	_Window	(Not Inspected)	Elec	tric/Split	X Leak noted at: Basement-furnac
Inspected	X Rep	airInv	estigate _	_Not Inspected	Not	Applicable	
Recommend	to have serv	viced <u> </u>	kes noise	Exterior unit no	ot level	Not operating	X Leak noted at: Basement-furnac
Cover dama	igedSh	nort cycling	Air flo	w at outside unit o	bstructed	Freon lines no	ot insulated
							No pad installed below unit
							unit is not operating
				heat pump units			de temperature is below 60 degrees.
"During winter	r montus tu	e inspector ca	annot chec	k air conditioner	unit for	operation if outsi	de temperature is below of degrees.
Plumbing:							
WATER HEA	ATER:						
		ent Size	gallons: 8	0 Enclo	sed coul	d not determine	Gas X Electric
X Inspected	Rena	ir Inve	stigate	Not Inspected	Not A	Applicable	Gas X_Electric
Leak noted a	nt:		Rust no	oted at:		-ppemere	
No relief val	ve Reli	ef valve not p	iped to floo	or May have	limited li	ife Vent flue	_ damaged at:
Electrical co	ver panel mi	issing No	expansion t	ank installed	Excessiv	e corrosion at:	
Improper/Ex	posed/Splice	ed wiring:				No	t operating Pilot not lit
Notes:							
WATER LIN	ES: Pipe o	composition:	_X_Co	pperCPVC	Gal	lvanizedPoly	butyleneQuestPex
MAIN WATE	ER CUT-OF	F LOCATE	O AT:	Basement at bot	tom of st	airway	Unknown
							_
X Inspected	Repa	ir Inve	stigate	Unknown _Not Inspected	Not A	Applicable	
Pressure no	t adequate _	Leak(s) at:		•	Cor	roded cut off valve	
Untested va	lve Pipe	es need insula	tionC	orrosion noted at:	<u> </u>	Pipes nearing	y/At end of life expectancy
Water hamm	ner noted (ne	eds water han	nmer arrest	er) Pipes nee	ed more su	apport Disco	oloration noted in water throughout
Pressure too	high/low _	Volume res	triction not	ed at:	.	Some pipes	have been replaced
	ucet leaks at	top cap/in wa	ll while op	erating/drips conti	ınually/ıs	not operating at:_	
Notes:	os all autoui	au basa bib f	awaata laal	at handlas whan	. ahaaltad	l Inspector does	not about boso bibs that are
				to prevent pipes			not check hose bibs that are
connected to g	aruen noses	during wind	er months	to prevent pipes	ii viii vui	sting.	
DRAIN LINE	S. Pine co	omposition:	Y PV	ARS	Calvan	ized Cast ir	on.
				Not Inspected			on .
							yPipes not repaired properly at:
No slant on	pipes at:	N	eed more s	upport at:	8	Could not dete	ermine where pipes drain to
Corrosion no	oted Son	ne pipes have	been replac	ced Improper	r slant on	pipesVent pi	pe does not penetrate above roof level
Notes:			•				•
LAUNDRY R	оом/Ехт	ERIOR VEN	T HOODS	S:			
				Not Inspected			
Leak/Drip no	oted at:		Lir	nited room at plur	nbing	_Recommend havi	ng a pan installed under washer
Corrosion no	oted at:			Electrical outlet n	ot tested	Outlet missin	g at: vent needs cleaned on exterior
Dryer not ve	ented to exter	riorVent	hose apart	missing at:		Dryer	vent needs cleaned on exterior
Vent hood d	amaged/miss	sing on exterio	or				
Notes: *Washers, dry	ions and the	in duain lines	ana nat ta	stad			
vv ashers, ury	cis and me	n uram mies	are not te	sicu.			

Thursday, June 23, 2016 Page 17 of 21

KITCHEN/APPLIANCES/PLUMBING:

DISHWASHER: X Inspected Not Inspected Not Applicable Not operating Door damaged Damaged inside Door gasket damaged No water/power Missing hardware Spray arm broken Leak noted Needs to be secured to counter Water won't drain Rust Older unit Notes:
GARBAGE DISPOSAL: InspectedRepairInvestigateNot Inspected _X Not ApplicableNot operatingMakes noiseCorrosionOlder unit, may have limited lifeWiring exposed/splicedJammed Notes:
*View restricted due to storage X InspectedRepairInvestigateNot InspectedNot Applicable Sink chipped /damagedSpray head leaksLeak below sinkCorrosion notedLow volume hot /cold Leaks at handle/spoutMissing handleP- trap not plumbed properlyPipes not repaired properly Spray head not operatingWater hammer notedDrips/Runs continually/sporadicallyDrains slowly Notes:
KITCHEN COUNTER/CABINETS: TYPE: X Formica Tile Corian Granite Concrete Stone Wood Other X Inspected X Repair Investigate Not Inspected Not Applicable Chipped/cracked Damaged Cracked tiles Moderate/heavy wear Damaged/Missing doors/drawers Missing handles/knobs Scratches noted Moisture stains Damaged frames Loose X Off track Counter top not secured to cabinet/cabinet not secured to wall/loose Burn marks on counter top Missing Notes: Refer to summary pages.
RANGE/OVEN: Type: x _ Electric _ Gas Electric oven/ gas stove (dual fuel) x _ Inspected _ Repair Investigate _ Not Inspected Not Applicable Element(s) not operating _ Door broken _ Knobs missing _ Drip pans missing _ Door won't close properly Not plugged in; not checked during inspection Not operating Pilot won't light Missing oven rack(s) No anti-tipping device installed on range _ Fan not operating Light not operating Notes:
MICROWAVE/HOOD FAN/DOWNDRAFT: InspectedX RepairInvestigateNot InspectedNot ApplicableNot operatingDamagedMissing filtersLight(s) not operatingNot vented properlyX Makes noiseExhaust fan noisyNot enough clearance at range and microwave (should be at least 15 inches) Notes: Refer to summary pages.
TRASH COMPACTOR: InspectedX_RepairInvestigateNot InspectedNot Applicable X_Not operatingDamagedOperates, no trash to compact Notes: Refer to summary pages.
UTILITY SINKS/WET BAR SINKS: InspectedRepairInvestigateNot Inspected _X Not ApplicableSink faucet leaks at: Leak below sink at: Limited room at plumbing Notes:

Thursday, June 23, 2016 Page **18** of **21**

BATHROOMS/PLUMBING/VENTILATION:

LOCATIONS: #1 Hall (half)-	1 st floor #2 Master #3 Hall (full)-1 st floo	or #4 2 nd floor Shared
TOILETS: InspectedX_RepairLoose at floor:Moisture at toilet: X_Runs continually: Full Notes: Refer to summary pages.	InvestigateNot InspectedNot ApplicableNeeds wax seal:Does not flush properly:Cracked/Broken:	Ball cock in tank needs adjusted: Flush handle broken: Leaks:
SINKS: View restricted due to storage X Inspected Repair Corrosion under sink: Cracks noted: Runs/Drips continually: Missing: Notes:		Leak below sink: Drains slowly: Drain stopper missing: Improper P-trap:
TUBS: X InspectedRepairDamaged:Leak at faucet handle:Handle broken:Corrosion noted:Drips/runs continually: Notes:		Jetted tub is not operating: Jetted tub jet(s) not operating: Shower diverter does not divert wate Leaks at shower diverter: Low/No volume:
SHOWERS: X Inspected Repair Leak at faucet handle: Handle broken: Corrosion noted: Leaks at bottom of surround: Notes:		Grout missing between tiles Doors damaged: e simultaneously:
BATHROOM/FLOORING/W. X Inspected Repair Cracks noted: Weak sub-floor/rot: Stains on floor: Notes:	ALLS/CABINETS: InvestigateNot InspectedNot Applicable Cabinet not secured to wall: Water present: Other:	Cabinet door damaged:Cabinet drawer off track:Counter top not secured to cabinet:
Exhaust fan not operating:	InvestigateNot Inspected Not Applicable Noisy: Exhaust fan light is not operating: tt fan not operating: Missing: Cover	· damaged:

Thursday, June 23, 2016 Page 19 of 21

INTERIOR/DOORS/WALLS/CEILINGS/FLOORING/STAIRWAYS:

Interior Doors:	
X Inspected Repair Investigate Not Inspected	Not Applicable
Rubs/sticks at jambs at: Won't	
Won't latch at: Holes	s noted in door(s) at:
Needs adjustment at: Drags	s on carpet/floor at:
Damaged at:Door	knob not operating at:
Off track at:	knob receiver sticks at:
Missing hardware/door at:	MIOO TOUTHOU SHOULD WE.
Notes:	
<u></u>	
Interior Walls:	
TYPE: X Drywall Plaster X Wallpaper X P	anelingWoodFabricColumnsOther
X Inspected Repair Investigate Not Inspected	Not Applicable
X Cracks noted at: Some-throughout	_ Fungus noted at:
Moisture stains at: Hole	es noted at:
Missing/Damaged/Loose at: EV	idence of patching at:
Notes:	
* Some interior walls could not be accessed due to storage.	
Interior Ceilings:	
TYPE: X Drywall Plaster X Drywall spray	Wood Tiles/Celotey X Other-Paneling
Inspected _X_Repair _X_InvestigateNot Inspecte	Not Applicable
X Moisture stains at: Half bath	Y Dry Wet Unable to determine
Cracks noted at:	Enumer noted at:
Cracks noted at: Holes noted at:	Y Sagging noted at: Den 2 nd floor hallway
	A Sagging noted at. Den,2 noor nanway
Notes: Refer to summary pages.	
tvotes. Refer to summary pages.	
Iverprop Er copyrg	
Interior Flooring:	
TYPE: X Carpet X Wood X Sheet goods/vinyl	TileWood laminate Parquet Brick Other
X Inspected Repair Investigate Not Inspected	
Carpet needs stretching at:	Damaged/Missing at:
Wood floor damaged at:	X Uneven floor at: Some-throughout
Damaged at:	Weak floor at:
Cracked/broken/loose tile at:	Squeaks/Pops noted at:
Notes:	
* Some interior floors could not be accessed due to storage.	
Interior Stairs:	
TYPE: Carpet WoodX Carpet and wood	Other
	Not Applicable
	
Handrail too low/high at: Low overhead clearance (no standard) at:	Handrail/Guardrail missing/loose at:
	Opening too small at:
Wood/carpet damaged/loose at:	Rise/run not to standards at:
	Nails popped at:
Notes:	

Thursday, June 23, 2016 Page 20 of 21

WINDOWS/EXTERIOR DOORS/COMMENTS:

Comments:

WINDOWS:		
MATERIALS: X Wood Metal Vinyl W	ood interior-metal/vinyl exterior	
TYPE: X Double hung Sliding Casement X F	Fixed Single hung Jealousy Roll out	
Inspected X Repair Investigate Not Inspe	ected Not Applicable	
Broken/cracked/missing glass at: Dual pane seal broken (fogged) at: X Won't open/close/lock at: Some-throughout Window non-operational at:		
X Won't open/close/lock at: Some-throughout	Window non-operational at:	
Locks missing/broken at:	Cranks/Handles missing/broken/stripped at:	
Sash/Balancer cords missing/broken at:	Window sash is off of balancer at:	
Glazing damaged at:	X Sills damaged at: Some-perimeter	
Screens missing at: X Moisture/Insect damage at: Center stiles-perimeter-some	Fungus noted on interior of windows	
X Moisture/Insect damage at: Center stiles-perimeter-some	Balancers weak (due to age)	
Brick molding damaged at: X Window sash damaged at: Some-perimeter	Tilt brackets broken at:	
X Window sash damaged at: Some-perimeter	Window needs a window well installed at:	
Notes: Refer to summary pages.		
*The presence or absence of storm windows was not checked during inspection.		
EXTERIOR DOORS:		
TYPE: X Wood/glass X Metal/glass X Glass slid	ling Panel Fiberglass	
Inspected X Repair Investigate Not Inspe		
Threshold damaged/loose at:		
Won't latch/close/open/lock at: Lock not operating/broken/missing hardware at:	Moisture damage at: V. Jamba damaged at: Recoment	
Weather strinning damaged/missing natural at.	Center stile moisture damaged at:	
Weather stripping damaged/missing at: X Glass pane broken/damaged/fogged at: Most glass sliding do	Can see light to exterior around door at:	
Rubs at jambs at:		
Notes: Refer to summary pages.	M Difficult to operate at: Deli	
Notes: Refer to summary pages.		
*Sprinkler systems not included in inspection.		
*Obscured areas on exterior as far as roof systems, shingles and grade during fall/winter months.		
Observed areas on exterior as far as roof systems, similares and grade during fail whiter months.		
Interior Systems not included during inspection:		
Intercom Systems		
Security Systems		
Elevators		
Dumbwaiters		
Sauna/Steam rooms		
Detached Sheds/Buildings		
Detached Sheds/Dundings		
Miscellaneous Notes:		

Thursday, June 23, 2016 Page 21 of 21